

Serial no.	BS-000278
District	Yau Tsim Mong
Address	Wall of pedestrian subway across Peking Road (near Kowloon Park Drive)
Key issue(s)	Graffiti

Before




After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000279
District	Yau Tsim Mong
Address	Junction of 22 Arran Street and Canton Road
Key issue(s)	Disposal of construction waste

Before




After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000280
District	Yau Tsim Mong
Address	Tung On Street (outside Tung On Street Rest Garden)
Key issue(s)	Disposal of construction waste

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000281
District	Yau Tsim Mong
Address	Granville Road near Chatham Road South (underneath of the footbridge)
Key issue(s)	Disposal of construction waste

Before




After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000282
District	Yau Tsim Mong
Address	Rear lane of Chungking Mansion, 44 Nathan Road (section between Nathan Road and Minden Row)
Key issue(s)	Disposal of construction waste

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000283
District	Yau Tsim Mong
Address	Planters on Salisbury Road near Salisbury Road Garden
Key issue(s)	Graffiti

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000285
District	Yau Tsim Mong
Address	Market Street Refuse Collection Point
Key issue(s)	Illegal refuse deposit

Before




After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000286
District	Yau Tsim Mong
Address	149-169 Tai Kok Tsui Road (near entrances of Chung Ying Building and Chung Mei Building)
Key issue(s)	Water dripping from air-conditioners

Before




After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000287
District	Yau Tsim Mong
Address	Vicinity of Tsing Shui Building, Tai Kok Tsui Road
Key issue(s)	Environmental hygiene problem

Before



After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000292
District	Yau Tsim Mong
Address	18 Tong Mi Road (walkway outside Skyline Tower)
Key issue(s)	Accumulation of styrofoam boxes

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000294
District	Yau Tsim Mong
Address	Vicinity of Yau Ma Tei Market
Key issue(s)	Accumulation of styrofoam boxes

Before



After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000295
District	Yau Tsim Mong
Address	Area outside 73-143 Tai Kok Tsui Road (under the flyover of West Kowloon Corridor)
Key issue(s)	Accumulation of styrofoam boxes

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000296
District	Yau Tsim Mong
Address	75-119 Lai Chi Kok Road
Key issue(s)	Rear lane hygiene problem

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000297
District	Yau Tsim Mong
Address	Rear lane of Tsui Yuen Mansion (Phase 1), 22-28 Kwong Wa Street
Key issue(s)	Rear lane hygiene problem

Before



After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000298
District	Yau Tsim Mong
Address	Rear lane of 14-44 Hankow Road
Key issue(s)	Rear lane hygiene problem

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000299
District	Yau Tsim Mong
Address	Rear lane of 9-13 Hau Fook Street
Key issue(s)	Rear lane hygiene problem

Before



After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000300
District	Yau Tsim Mong
Address	Rear lane of 37U Jordan Road
Key issue(s)	Rear lane hygiene problem

Before




After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000301
District	Yau Tsim Mong
Address	Rear lane of 64-76 Woosung Street
Key issue(s)	Rear lane hygiene problem

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000302
District	Yau Tsim Mong
Address	Rear lane between Woosung Street and Nanking Street (near David Mansion)
Key issue(s)	Rear lane hygiene problem

Before




After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000303
District	Yau Tsim Mong
Address	Rear lane of Hung Wai Building, 3-5 Fa Yuen Street
Key issue(s)	Rear lane hygiene problem

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000309
District	Yau Tsim Mong
Address	Junction of Fuk Tsun Street and Fir Street (outside Fuk Hing Building), Tai Kok Tsui
Key issue(s)	Shop front extension

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000312
District	Yau Tsim Mong
Address	Yau Ma Tei Typhoon Shelter (near walkway to West Kowloon Cultural District)
Key issue(s)	Illegal refuse deposit

Before




After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000313
District	Yau Tsim Mong
Address	Rear lane of Ichang Street (adjacent to Ashley Mansion), Tsim Sha Tsui
Key issue(s)	Rear lane hygiene problem

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000314
District	Yau Tsim Mong
Address	Rear lane of Tai Fong Building and Tai Chung Building, 55 Ivy Street, Tai Kok Tsui
Key issue(s)	Rear lane hygiene problem

Before



After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000316
District	Yau Tsim Mong
Address	Rear lane of Tai Kung Building, 117 Tai Kok Tsui Road
Key issue(s)	Rear lane hygiene problem

Before



After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000320
District	Yau Tsim Mong
Address	Rear lane of 3A-3B Waterloo Road (section between Waterloo Road and Pitt Street)
Key issue(s)	Rear lane hygiene problem

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000321
District	Yau Tsim Mong
Address	Rear lane of Kam Tong Building, 1 Waterloo Road (section between Waterloo Road and Pitt Street)
Key issue(s)	Rear lane hygiene problem

Before




After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000324
District	Yau Tsim Mong
Address	Rear lanes, restaurants and shops between Tung On Street and Canton Road
Key issue(s)	Disposal of construction waste; rear lane hygiene problem

Before




After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000325
District	Yau Tsim Mong
Address	Vicinity of the junction of Wai On Street and Man On Street (outside the entrance of the substation), Tai Kok Tsui
Key issue(s)	Disposal of construction waste

Before




After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000326
District	Yau Tsim Mong
Address	Vicinity of Tung On Street (near the basketball court)
Key issue(s)	Disposal of construction waste

Before




After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000327
District	Yau Tsim Mong
Address	Vicinity of staircases of Dundas Street footbridge/Ferry Street footbridge
Key issue(s)	Disposal of construction waste

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000328
District	Yau Tsim Mong
Address	Vicinity of MTR Austin Station (near Jordan Road)
Key issue(s)	Congregation of wild birds and environmental hygiene problems

Before



After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000329
District	Yau Tsim Mong
Address	Charming Garden Refuse Collection Point
Key issue(s)	Rodent infestation

Before




After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000330
District	Yau Tsim Mong
Address	Vicinity of Block 1, Charming Garden, Hoi Ting Road
Key issue(s)	Environmental hygiene problem

Before



After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000331
District	Yau Tsim Mong
Address	Vicinity of Tung On Street and Ferry Street
Key issue(s)	Environmental hygiene problem

Before




After (Photo(s) taken in February 2025)




Removed from the list of hygiene black spots in March 2025

Serial no.	BS-000332
District	Yau Tsim Mong
Address	Vicinity of the junction of Tai Kok Tsui Road and Mei On Street
Key issue(s)	Environmental hygiene problem; rodent infestation

Before



After (Photo(s) taken in February 2025)



Removed from the list of hygiene black spots in March 2025